



**Hubshell**

	<b>A</b> NDS Flange $\varnothing$	<b>B</b> NDS Center to Flange	<b>C</b> DS Center to Flange	<b>D</b> DS Flange $\varnothing$
135/142	58mm	35mm	22mm	60mm
148	58mm	38mm	25mm	60mm
150/157	58mm	42mm	29mm	60mm
SS	58mm	34mm	36mm	60mm
SS 148	58mm	38mm	39mm	60mm
170/177	58mm	45mm	39mm	60mm

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*