



Hubshell

100

A NDS Flange \varnothing
36mm

B NDS Center to Flange
38mm

C DS Center to Flange
38mm

D DS Flange \varnothing
36mm

For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing